

DO NOT USE VEHICLE PLATE REMOVED

THE MAIDSTONE BOROUGH COUNCIL

APPENDIX 2

HACKNEY CARRIAGE AND PRIVATE HIRE VEHICLE INSPECTION REPORT SHEET

Make & CC: TX4 Recorded Mileage: 46785 Year of Manufacture: 2009 Plate No: H25
 Reg. No: GX09HKS Colour: WHITE Chassis No: SCRT285MESC206777

*The Test will be terminated if any defect which causes the vehicle to be dangerous or unroadworthy is found. Any defects in sections marked with asterisks will result in automatic failure.

	Pass	Fail		Pass	Fail
A BRAKES			F LIGHTING		
*1 Performance: Footbrake		✓	*1 Head/side/rear/fog	✓	
*2 " Handbrake	✓		*2 Stop lamps	✓	
*3 Condition of mechanical components	✓	✓	*3 Reflectors	✓	
*4 Pipes and hoses	✓		*4 Head lamps	✓	
*5 Servos, vacuum pumps and hydraulic components	✓		5 Direction indicators & hazard lamps	✓	
*6 Controls in drivers cabin	✓		6 Other lamps	✓	
B STEERING			G DRIVERS COMPARTMENT		
*1 Turning circles (FX4 types only)	✓		*1 Seat belt	✓	
*2 Linkage			2 Driver's seat	✓	
*3 Controls			3 Controls	✓	
*4 Mechanism			*4 Fire extinguisher	✓	
*5 Power steering			5 Windscreen & interior mirror	✓	
*6 Stub axles, kingpins, wheel bearings			*6 Windscreen washers & wipers	✓	
C TYRES, WHEELS			7 Radio & Mobile data equipment	✓	
*1 Tyres			8 Vehicle Excise Licence & Insurance	✓	
*2 Wheels			9 Luggage & compartment trim	✓	
*3 Wheel bearings			H BODY/PAINTWORK		
D CHASSIS, UNDERPARTS			1 Bodywork condition	✓	
*1 Frame			2 Paintwork condition	✓	
*2 Under panels, sills & body mountings			*3 Door locks	✓	
*3 Exhaust			4 Boot lid & compartment	✓	
*4 Engine underparts			5 Glass	✓	
*5 Clutch & gearbox underparts			6 Tinted Glass -- min 75% front min 70% side/rear	✓	
*6 Rear axle			7 Advertisements	✓	
*7 Prop shaft			8 Badges/motifs	✓	
*8 Fuel tank & pipelines			9 Bumpers/over-riders	✓	
*9 Front suspension			10 Index plates	✓	
*10 Rear suspension			11 External mirrors	✓	
E ENGINE COMPARTMENT			I CARRIAGE COMPARTMENT		
1 Cooling system	✓		*1 Seat belts (from 1.4.87)	✓	
2 Drive belts	✓		2 Headlining's	✓	
*3 Fluid reservoirs	✓		3 Interior fittings	✓	
4 Battery	✓		4 Seats	✓	
5 Wiring/fuses	✓		5 Automatic door locking (FX4 types only)	✓	
6 Bonnet security	✓		J ROAD TEST		
7 Alternator	✓		*1 Road test	✓	
8 Injector pump	✓		2 Smoke/fume emission	✓	
9 Fuel lift pump	✓		3 Transmission	✓	
*10 Fuel cut off signs	✓		4 Ride/knock/rattles	✓	
11 Air filter	✓		5 Speedometer	✓	
12 Bulk head	✓		K GENERAL		
13 Inner panels	✓		1 Wheelchair facilities (FX4 types only)	✓	
14 Horn	✓		2 Ramps (FX4 types only)	✓	

STATION NO. 91500 JOB NO. 9209 RETEST N/A DATE 22/06/22

COMMENTS

SIGNATURE OF TESTER

[Redacted Signature]

EAK FROM OS/R BRAKE DRUM ✓
 STEERING BOX MOUNTING CRACKED ✓
 PROPSHAFT CENTRE BEARING ✓

9250

EXCESSIVE CORROSION OS INNER + OUTER SILL PANEL ✓
 FRONT / REAR BRAKE PIPE ✓
 INNER WHEEL ARCH OS
 OS/R WITHIN SEAT BELT
 MOUNTS. ✓